



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(~~EA~~ OR UIC)

Date of Test 10-6-03 Operator BC + D operating Inc API # 30-081-20152

Property Name South Hoshak Unit Well # 39 Location: Unit H Sec 12 Twn 17 Rge 9

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection X
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): N TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to 450 psi. for * mins. Test ~~passed~~ failed


REMARKS: Well lost 10% of pressure in less than 5 min - well
Shut in.

By Daniel R. Bird
(Operator Representative)

Witness Bruce Machi
(NMOCD)

(Position)

Revised 02-11-02



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-1000 10/6/03

TAKEN OFF 10:30 A M
CHART PUT ON 10:45 A M
LOCATION BC & D Operating Unit # 39
REMARKS South Hospital Unit # 39
API # 30-031-20152

Domitilla
BC & D

PRINTED IN U.S.A.