



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/7/07 Operator CDX RIO, LLC API #30-039- 08081
Property Name Reames "A" Well No. 1 Location: Unit B Section 24 Township 26N Range 6W
Well Status (Shut-In or Producing) (Producing) Tubing 60 Intermediate Casing 78 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>Ø</u>		<u>78</u>		
10 minutes	<u>Ø</u>		<u>78</u>		
15 minutes	<u>Ø</u>		<u>78</u>		
20 minutes					
25 minutes					
30 minutes					
				Steady Flow	
				Surges	
				Down to Nothing	
				Nothing	
				Gas	
				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE

REMARKS: Blew down in 2 seconds



By Duane Harrison
Field Tech
(Position)

Witness Zel G. Ralston

E-mail address