



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-12-07 Operator CDX RIO, LLC API #30-039- 08098

Property Name Jicarilla "C" Well No. 3 Location: Unit I Section 23 Township 24N Range 5W

Well Status (Shut-In or Producing) (Shut-In) Tubing 188 Intermediate - Casing 245 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>Ø</u>		<u>245</u>		
10 minutes	<u>Ø</u>		<u>245</u>		
15 minutes	<u>Ø</u>		<u>245</u>		
20 minutes					
25 minutes					
30 minutes					
				Steady Flow	
				Surges	
				Down to Nothing	<u>X</u>
				Nothing	
				Gas	<u>X</u>
				Gas & Water	
				Water	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE _____

REMARKS:

Blew down in 3 seconds



By Duane Harrison

Witness _____

Field Tech
(Position)

E-mail address _____