

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6-12-07 Operator_CD	OX RIO, LLC_API #30-039 <i>O8</i> ]	39
Property Name Jicavilla "C" Well No. 4	Location: Unit <u>F</u> Section <u>24</u> Townsl	nip <u>UN</u> Range <u>5</u> W
Well Status (Shut-In of Producing) Tubing 159 Int	ermediate — Casing 151 Bradenh	ead_2_
OPEN BRADENHEAD AND INTERMEDIATE TO A	TMOSPHERE INDIVIDUALLY FOR 15	MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes   151	Steady Flow	
10 minutes 151	Surges	
15 minutes # 151	Down to Nothing X	
20 minutes	Nothing	
25 minutes	Gas	
30 minutes	Gas & Water	
	Water	
If bradenhead flowed water, check all of the descriptions that	at apply below:	2274.25.0
CLEAR FRESH SALTY S	ULFUR BLACK	22324252623
5 MINUTE SHUT-IN BRADENHEAD O	NTERMEDIATE	72324252627303031 RECEIVED 3031 JUL 712007 - 1
REMARKS: Blew down in 2	Second's	CONS. DIV. DIST. 3
	To a second	21101881884
		-0.83
By Duane Harrison W	Vitness	
Field tech		
(Position)		
E-mail address		