

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6.8.0	27	Operator_0	CDX RIO, LLC_AP	I #30-039- <u>//<i>8</i></u>	37
Property Name Jicar	illa A Well	No. 5	Location: Unit_ <u>&amp;</u>	Section 20 Towns	ship <u>ILN</u> Range <u>SW</u>
Well Status (Shut-In or	Producing) Tub	ing 109	Intermediate Ca	sing <u>//4</u> Braden	head Ø
OPEN BRADENHEAI	O AND INTERME	DIATE TO	ATMOSPHERE INDI	VIDUALLY FOR 1	5 MINUTES EACH
TIME BRADENHEAD	PRESSURES: INTERMEDIATE	CASING	_	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes Ø		114	_ Steady Flow		
10 minutes		114	Surges		
15 minutes Ø		114	_ Down to Nothi	ng	
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			_ Gas & Water_	,	23242520
			Water		DE ST
If bradenhead flowed water	r, check all of the de	scriptions (	that apply below:	17 18	JULIVED 3
CLEAR FI	RESHSAL	TY	SULFUR BLAC	CK 7.817.18.73.	OIL CONS. DIV. DIST
5 MINUTE SHUT-IN BRADENHEAD			INTERMEDIATE	<b>\</b>	24 51 1101 88 TO BE
REMARKS:					
	.,,,		_		
By Duane Ha	wisou		Witness		
E-mail address_					