

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/12/67 Operator_CDX RIO, LLC_API #30-03923/64						
Property Name 1/c-15/ Well No. 5 Location: Unit Section 9 Township 16 Range 25						
Well Status (Shut-In or Producing) Tubing 124 Intermediate Casing 125 Bradenhead 6						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME BRA		PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	0	8	125#	Steady Flow		
10 minutes	6		105#	Surges		
15 minutes	0	0	125#	Down to Nothin	g	
20 minutes	END	Test		Nothing	X	X
25 minutes				Gas		
30 minutes		4		Gas & Water	/-/	2232425262
				Water		7500
If bradenhead flowed water, check all of the descriptions that apply below:						
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE INTERMEDIATE						
REMARKS: No pressure rudy & Drala heal & Dr termediate						
	1					
By Hay	Jamos		Wit	ness		
(Positio	Tuh.					
E-mail address						