



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-14-2007 Operator CDX RIO, LLC API #30-039- 06071

Property Name Jicarilla Cont. 146 Well No. 9 Location: Unit M Section 10 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 61 # Intermediate N/A Casing 104 # Bradenhead 0 #

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>104</u> #	Steady Flow	
10 minutes	<u>0</u>		<u>104</u> #	Surges	
15 minutes	<u>0</u>		<u>104</u> #	Down to Nothing	
20 minutes				Nothing <u>0</u> #	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS: Bradenhead had no vapor or pressure upon opening of
1" valve.

By W. J. Smith

Witness _____

Field Technician

(Position)

E-mail address _____

