



and
NATURAL RESOURCES
DEPARTMENT

1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-15-2007 Operator CDX RIO, LLC API #30-039- 06084
Property Name Jicarilla Cont. 146 Well No. 4 Location: Unit J Section 10 Township 25N Range 5W
Well Status (Shut-In or Producing) Tubing 94# Intermediate N/A Casing 95# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0#</u>		<u>95#</u>	Steady Flow	
10 minutes	<u>0#</u>		<u>95#</u>	Surges	
15 minutes	<u>0#</u>		<u>95#</u>	Down to Nothing	
20 minutes				Nothing	<u>X</u>
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Bradenhead had no pressure or vapor upon opening
of 1" valve.

By W. J. Smith
Field Technician
(Position)

Witness NONE

E-mail address _____

