



and
NATURAL RESOURCES
DEPARTMENT

1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-15-2007 Operator CDX RIO, LLC API #30-039- 06112
Property Name Jicarilla Cont. 146 Well No. 3 Location: Unit D Section 10 Township 25N Range 5W
Well Status (Shut-In or Producing) Tubing 68# Intermediate N/A Casing 70# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0#</u>		<u>70#</u>		
10 minutes	<u>0#</u>		<u>70#</u>		
15 minutes	<u>0#</u>		<u>70#</u>		
20 minutes				<u>X</u>	
25 minutes					
30 minutes					
				Steady Flow	
				Surges	
				Down to Nothing	
				Nothing	
				Gas	
				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0# INTERMEDIATE _____

REMARKS:

Bradenhead had no pressure or vapor upon opening of
the 1" valve.

By Walt

Witness NONE

Field Technician

(Position)

E-mail address _____

