



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/7/07 Operator CDX RIO, LLC API #30-039- 20037

Property Name Jico 151 Well No. 2 Location: Unit A Section 10 Township 26 Range 5

Well Status (Shut-In or Producing) Tubing 110 Intermediate N/A Casing 140⁺ Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>140⁺</u>	Steady Flow	
10 minutes	<u>0</u>		<u>140⁺</u>	Surges	
15 minutes	<u>0</u>		<u>140⁺</u>	Down to Nothing <u>X</u>	
20 minutes	<u>END</u>	<u>Test</u>		Nothing <u>X</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

No pressure buildup on Bradenhead.

By Ray Amador
Field Tech.
(Position)

Witness _____

E-mail address _____

