



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test June 18, 2007 Operator CDX RIO, LLC API #30-039- 22524
Jicarilla Cont. 148 # 24 Location: Unit D Section 14 Township 25N Range 5W
Property Name _____ Well No. _____
Well Status (Shut-In or Producing) Tubing 69[#] Intermediate NA Casing 76[#] Bradenhead -1/2[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>	<u>NA</u>	<u>76</u> [#]
10 minutes	<u>0</u>	<u>NA</u>	<u>76</u> [#]
15 minutes	<u>0</u>	<u>NA</u>	<u>76</u> [#]
20 minutes			
25 minutes			
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas	<u>X</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

BH had less than 1/2[#] bled off to zero upon opening of 1" ball valve, no action afterwards.

By Robby R. Datchman
PROD. TECH
(Position)

Witness NONE

E-mail address _____

