



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

# BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-11-2007 Operator CDX RIO, LLC API #30-039- 23567  
Jicquilla cont. 146  
Property Name \_\_\_\_\_ Well No. 13-R Location: Unit J Section 9 Township 25N Range 5W  
Well Status (Shut-In or Producing) Tubing 54# Intermediate N/A Casing 140# Bradenhead -1#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>		<u>140#</u>
10 minutes	<u>0</u>		<u>140#</u>
15 minutes	<u>0</u>		<u>140#</u>
20 minutes			
25 minutes			
30 minutes			

BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow _____	
Surges _____	
Down to Nothing <u>X</u>	
Nothing _____	
Gas _____	
Gas & Water _____	
Water _____	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

Bradenhead vented down to nothing after a 10 minute venting.

By [Signature]  
Field Technician  
(Position)

Witness NONE

E-mail address \_\_\_\_\_

