



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test _____ Operator CDX RIO, LLC API #30-039- 27840
Property Name SIC 108 (A-D) Well No. E8P Location: Unit G Section 13 Township 24 Range 5
Well Status (Shut-In or Producing) Tubing 145 Intermediate N/A Casing 140 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>Ø</u>		<u>160</u> ^H	Steady Flow _____	
10 minutes	<u>Ø</u>		<u>160</u> ^H	Surges _____	
15 minutes	<u>Ø</u>		<u>160</u> ^H	Down to Nothing _____	
20 minutes	<u>END</u>	<u>Test</u>		Nothing <u>✓</u>	
25 minutes				Gas _____	
30 minutes				Gas & Water _____	
				Water _____	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

Bradenhead, no psi reading.

By Ray Dawson

Witness _____

(Position)

E-mail address _____

