



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test June 08, 2007 Operator CDX RIO, LLC API #30-039- 05569

Property Name Jicarilla Gas Com 35 B#1 Well No. _____ Location: Unit H Section 11 Township 24N Range 5W

Well Status (Shut-In or Producing) Tubing 81[#] Intermediate NA Casing 710 Bradenhead -1[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>	<u>NA</u>	<u>710</u> [#]
10 minutes	<u>0</u>	<u>NA</u>	<u>710</u> [#]
15 minutes	<u>0</u>	<u>NA</u>	<u>710</u> [#]
20 minutes			
25 minutes			
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

BH had less than 1", bled to zero upon opening of 1" ball valve. No flow afterwards. Tested for 10 MINUTE

By Polby R. Hatchman
PROD. Technician
(Position)

Witness NONE

E-mail address _____

