



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/5/07 Operator CDX RIO, LLC API #30-039- 21674

Property Name Jico 151 Well No. 8 Location: Unit 0 Section 3 Township 24 Range 5

Well Status (Shut-In or Producing) Tubing 110th Intermediate Ø Casing 22nd Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>Ø</u>	<u>Ø</u>	<u>220</u>
10 minutes	<u>Ø</u>	<u>Ø</u>	<u>220</u>
15 minutes	<u>Ø</u>	<u>Ø</u>	<u>220</u>
20 minutes	<u>End Test</u>		
25 minutes			
30 minutes			

BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

No pressure held on Braden head

By Roy Huns

Witness _____

Field Tech.

(Position)

E-mail address _____

