



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-12-07 Operator CDX RIO, LLC API #30-039- 23068

Property Name JIC. Gas Com 155 Well No. A#1 Location: Unit H Section 32 Township 26N Range 5W

Well Status (Shut-In or Producing) Tubing 105 Intermediate Casing 108 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>108</u>	Steady Flow <u> </u>	
10 minutes	<u>0</u>		<u>108</u>	Surges <u> </u>	
15 minutes	<u>0</u>		<u>108</u>	Down to Nothing <u> </u>	
20 minutes				Nothing <u> </u> ✓	
25 minutes				Gas <u> </u>	
30 minutes				Gas & Water <u> </u>	
				Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Gloria Vigil Witness

(Position)

E-mail address

