



and  
NATURAL RESOURCES  
DEPARTMENT

1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-21-2007 Operator CDX RIO, LLC API #30-039- 05975  
Property Name Jicarilla Cont. 148 Well No. 16 Location: Unit N Section 14 Township 25N Range 5W  
Well Status (Shut-In or Producing) Tubing 75# Intermediate N/A Casing 75# Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	0		75#	Steady Flow	
10 minutes	0		75#	Surges	
15 minutes	0		75#	Down to Nothing	
20 minutes				Nothing	X
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

Bradenhead had no pressure or vapor upon opening of 1" valve.

By W. E. S.

Witness \_\_\_\_\_

Field Technician

(Position)

E-mail address \_\_\_\_\_

