



and
NATURAL RESOURCES
DEPARTMENT

1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm


BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-21-2007 Operator CDX RIO, LLC API #30-039- 06019
Property Name Jicarilla Cont. 148 Well No. 4 Location: Unit F Section 13 Township 25N Range 5W
Well Status (Shut-In or Producing) Tubing 55# Intermediate N/A Casing 65# Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	0		65#	Steady Flow	
10 minutes	0		65#	Surges	
15 minutes	0		65#	Down to Nothing	
20 minutes				Nothing	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Bradenhead had less than 1 pound of pressure and bled
down to nothing upon opening of 1" Valve.

By WES
Field Technician
(Position)

Witness NONE

E-mail address _____