

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178

FAX: (505) 334-6170 www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test_	6-25	-07 (	Operator_	CDX RIO, LLC_API	#30-039- <u>219</u>	28
Property Name Jic. Cowl. 147 Well No. 7 Location: Unit L Section 8 Township 25N Range 5W						
Well Status (Shut-In or Producing) Tubing 38 Intermediate Casing 52 Bradenhead O						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME BRA		RESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	0		52	Steady Flow		
10 minutes	0		52	Surges		
15 minutes	0		52	Down to Nothing	5	
20 minutes				Nothing	V	
25 minutes				Gas	(0	2324252623
30 minutes				Gas & Water	(0°22)	A 623
1,				Water	7 18 1	ECEIVED 8
25 minutes  Gas  Water  Water  If bradenhead flowed water, check all of the descriptions that apply below:  CLEAR FRESH SALTY SULFUR BLACK  5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE  101 12324252623  Water  Water  Water  FECEIVED  OIL CONS. DIV. DIST. 3  OIL CONS. DIV. DIST. 3  TOTAL CONS. DIV. DIST. 3						
CLEAR FRESH SALTY				SULFUR BLACK	— /gr.	C 10 C 10
5 MINUTE SHUT-IN BRADENHEAD O				INTERMEDIATE		0168793
REMARKS:						
. 1					gal	
		2.45-4.28				
	. /					
By FROVOR Vigil  Pumper  (Position)				Witness		
Position	per					
E-mail address						