



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT


(Submit 2 copies to above address)

Date of Test June 11, 2007 Operator CDX RIO, LLC API #30-039- 22566
Property Name Jicarilla Cont. 148 # Well No. 26 Location: Unit H Section 14 Township 25N Range 5W
Well Status (Shut-In or Producing) Tubing 86 # Intermediate NA Casing 136 # Bradenhead VACUUM

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>	<u>NA</u>	<u>136 #</u>
10 minutes	<u>0</u>	<u>NA</u>	<u>136 #</u>
15 minutes	<u>0</u>	<u>NA</u>	<u>136 #</u>
20 minutes			
25 minutes			
30 minutes			

BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS: BH had vacuum, down to nothing upon opening of 1" ball valve. No action afterwards.

By Dorothy R. Hatchman
Prod. Tech.
(Position)

Witness NONE

E-mail address _____