



and
NATURAL RESOURCES
DEPARTMENT

1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-21-2007 Operator CDX RIO, LLC API #30-039- 23655
Property Name Jicarilla Cont. 148 Well No. 32 Location: Unit D Section 14 Township 25N Range 5W
Well Status (Shut-In or Producing) Tubing 75[#] Intermediate N/A Casing 103[#] Bradenhead 2[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	0		103 [#]
10 minutes	0		103 [#]
15 minutes	0		103 [#]
20 minutes			
25 minutes			
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas	X	
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Bradenhead had 2 pounds of pressure upon opening of 1" valve and bled down to nothing in less than 5 seconds.

By Walt
Field Technician
(Position)

Witness NONE

E-mail address _____