



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

RCUD SEP 19 '07
OIL CONS. DIV.

MECHANICAL INTEGRITY TEST REPORT

DIST. 3

(TA OR UIC)

Date of Test 9/19/2007 Operator Burlington Resources API # 30-0 45-11411

Property Name Allison Unit Well # 1 POW Location: Unit C Sec 17 Twn 32 Rge 6

Land Type:

State _____
Federal _____
Private ☒ _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation ☒ _____

Temporarily Abandoned Well (Y/N): _____

MIT
TA Expires: 9-12-2012

Casing Pres. _____

Tbg. SI Pres. _____

Max. Inj. Pres. _____

Bradenhead Pres. 0

Tbg. Inj. Pres. _____

Tubing Pres. N/A

Int. Casing Pres. 0

Pressured annulus up to 670 psi. for 30 mins. Test passed/failed Failed

REMARKS:

10AM in hole & set packer - Load

PACKER 3031'

top pack 3064

By [Signature]
(Operator Representative)

Witness Henry Villanueva
(NMOCD)

Onsite Supervisor
(Position)

Revised 02-11-02

42

