Scorpion Drilling Company

PO Box 1951 Farmington New Mexico 87499 scorpiondrilling@advantas.net AP (505) 326-5601 Fax (505) 325-1786

September 11, 2007

Reference: Holcomb Oil and Gas Jacque #2 San Juan County New Mexico API No. 30-045-34409

A total of Five (5) deviation surveys were run using a SURE SHOT tool. These surveys were as follows:

Surface Hole -182' = 1 deg. Production Hole $-682' = 1 \frac{3}{4} \deg_{10} 990' = \frac{1}{2} \deg_{10} 1419' = 1 \deg_{10} 1866' = 1 \deg_{10}$

These surveys were given to Holcomb Oil & Gas Inc. for placement in the well file.

This is correct and accurate to the best of my knowledge.

Henry Valdez

President / General Manager Scorpion Drilling Company

RCVD SEP 24'07 OIL CONS. DIV. DIST. 3

ommission Expires February 24, 2010.