

## NEW MEXICO ENERGY, MUNERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District.ll//3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test	t -ep-10-0	Operato	r Kimbell operation	19 API #30-0 <u>.39-6</u>	72317
			E Location: Unit E S		
Well Status	(Shut-In or Producin	g) Tubing 520	Intermediate Casi	ng <u>114</u> Bradenh	ead_O
OPEN BR	ADENHEAD AND I	NTERMEDIATE	TO ATMOSPHERE INDIV	VIDUALLY FOR 15	MINUTES EACH
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	lacktriangle	124	Steady Flow		
10 minutes	0	124	Surges		
15 minutes	,	124	Down to Nothing	8	
20 minutes	0	124	Nothing		
25 minutes	0	124			
30 minutes	O	124	Gas & Water		
			Water	234	56789707
If bradenhead	l flowed water, check a	ll of the description	ns that apply below:	<b>5</b> 75	CEIVED S
CLEA	ARFRESH	SALTY	SULFUR BLAC	CK 88 RE	CEIVED 4757 CONS. DIV. DIST. 3
				A OIL	ONS. DIV. DIST. 3
5 MINUTE SI	HUT-IN BRADENH	EAD	INTERMEDIATE	- PEREN	CONS. DIV. DIST. 3
REMARKS					66660
By Eas	cl North	Witn	ess		
Pumpe	cl North				
(Posit	tion)				