Form C-103 State of New Mexico Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N French Dr, Hobbs, NM 87240 District II 30-045-23660 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE [] FEE  $\square$ 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S St Francis Dr., Santa Fe, NM 87505 E-3148-7 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Burroughs State DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH RCUD DCT 15'07 PROPOSALS.) 8. Well Number 1. Type of Well: OIL CONS. DIV. Oil Well Gas Well X Other 2. Name of Operator 9. OGRID Number Energen Resources Corporation 162928 10. Pool name or Wildcat 3. Address of Operator 2198 Bloomfield Highway, Farmington, NM 87401 Basin Dakota 4. Well Location 1450 South 1820 feet from the Unit Letter line and feet from the Township 26N Range County San Juan 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3/夏/盧州 Pit or Below-grade Tank Application X or Closure Pit type \_\_Drill Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_ Pit Liner Thickness: Below-Grade Tank: Volume\_\_\_\_\_bbls; Construction Material \_ 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. **TEMPORARILY ABANDON CHANGE PLANS PLUG AND ABANDONMENT** PULL OR ALTER CASING **MULTIPLE** CASING TEST AND COMPLETION **CEMENT JOB**  $\mathbf{x}$ OTHER: OTHER: repair casing leak 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion

or recompletion.

Energen Resources repaired the casing leak on the Burroughs State #1E as follows:

09/27/07 MIRU. NDWH. NU BOP. TOH with 2.375"tubing.

09/28/07 TIH with RBP & packer, set RBP @ 6000' & packer @ 5870'. Test RBP to 500 psi - ok. Isolate casing leak from 3552' - 3580'. Establish injection rate of 3/4 bbl/min @ 1200 psi. Packer set @ 3308'.

10/01/07 Squeeze casing leak with 75 sks 50/50 poz and 0.2% Halad-9.

10/02-03/07 Drill out cement to 6630'. Circulate hole. Test casing to 500 psi - ok.

10/04/07 TIH and clean out to RBP. TOH with RBP. TIH with scraper, clean out to 6176'.

10/05/07 TIH with 2.375" tubing, land @ 6148'. ND BOP. NUWH. Return to production

hereby certify that the information above is true and complete				
rade tank has been will be constructed or closed according to NMOCD g	guidelines 🗶	, a general permitor an (attach	ed) alternative OC	D-approved plan 🗌
SIGNATURE VICE DOMOKEY	TITLE	Regulatory Analyst	DATE	10/10/07
(\	E-mail ac	ddress: vdonaghe@e	nergen.com	

TITLE \_\_\_\_

Vicki Donaghey  $\mathcal{O}$ Type or print name

Deputy Oil & Gas Inspector.

District #3

OCT 1 5 2007

Telephone No. 505.325.6800

DATE

Conditions of Approval, if any:

For State Use Only

APPROVED BY