

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178

FAX: (505) 334-6170 www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4/14/05	Operator	evon	_API #30-0_ <u>3</u> 9	-24641
Property Name NEBU Well No. 42/A Location: Unit P Section 4 Township 301/2 Range 76				
Well Status (Shut-In of Producing) Tubing 12 Intermediate MA Casing 3 Bradenhead 8				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURES: TIME BRADENHEAD INTERMEDIATE	CASING	-	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes O N/A	3	Steady Flow		
10 minutes O	3	Surges		
15 minutes O	3	Down to Nothing		W/A
20 minutes		Nothing		
25 minutes		Gas		
30 minutes		Gas & Water		
		Water		C/40 III 71 K
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK BLACK				
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE ON CONT. S				
REMARKS: Tubing pressure MAY NOT be Accurate Danes				
To The Large Volume of water -				
		•		
By Tennett W. Vaugher	Witne	ss	N.	
Contractor - Ark Sales & Services INC (Position) Witness				
E-mail address				