



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-5-04 Operator Devon API #30-0 45-27353

Property Name NEBU Well No. 467 Location: Unit A Section 12 Township 30N Range 8W

Well Status (Shut-In or Producing) Tubing 1 Intermediate N/A Casing 2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>	<u>N/A</u>	<u>2</u>
10 minutes	<u>0</u>		<u>2</u>
15 minutes	<u>0</u>		<u>2</u>
20 minutes			
25 minutes			
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		<u>N/A</u>
Surges		<u>✓</u>
Down to Nothing		<u>✓</u>
Nothing	<u>✓</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Tubing Reading was taken from LCD Gage. (Due To Water)
Casing Reading was taken from LCD - No Access for Ext. Gage

By Denneth W. Vaughan

Witness

Contractor - ARK Sales & Services Inc.
(Position)

E-mail address

