

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test_	4-6-07	Operator 50	Chalk Dev Co.	_API #30-0_ 39	- 26441
Property Name	eSchalk 41	_Well No <u>2</u> _13_	_Location: Unit_N_S	Section_ & _Towns	hip <u> 25</u> Range <u>3</u>
Well Status (S	shut-In or Producing)	Tubing 80 In	ntermediate Cas	sing [00 Bradenl	nead O
OPEN BRAI	DENHEAD AND INTI	ERMEDIATE TO	ATMOSPHERE INDI	VIDUALLY FOR 15	MINUTES EACH
TIME BRA	PRESSURES			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		100	Steady Flow		
			Surges		
				XX	
		į.			
			Gas & Water		
			Water		
If bradenhead f	lowed water, check all o	f the descriptions th	nat apply below:		
CLEAR	FRESH	SALTY	SULFUR BLAC	K	
5 MINUTE SHUREMARKS:	UT-IN BRADENHEA	D	INTERMEDIATE	RECE	IVED 18910112
				CH CONS.	(19181A) ELL
By Ster	e ATENCIO		Witness		
FIELQ (Position	DE ATENCIO DECH				
E-mail address_					