



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-25-07 Operator Black Hills API #30-0 39 26728

Property Name Jic 29-3-14 Well No. 1 Location: Unit 13 Section 14 Township 29N Range 3W

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u> </u>	
Surges <u> </u>	
Down to Nothing <u> </u>	
Nothing <u>✓</u>	
Gas <u> </u>	
Gas & Water <u> </u>	
Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE


REMARKS:

NO surface equipment, NO separator & NO meter run, This well has
been permanently abandoned.

By Chris Hedberg
Pumper
(Position)

Witness

E-mail address Cherbauf@bhp.com



OCD files show Active.