



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-12-07 Operator Black Hills API #30-0 39 29264

Property Name Jic 30-3-33 Well No. 14 Location: Unit Section 33 Township 30N Range 3W

Well Status(Shut-In or Producing) Initial PSI: Tubing 40 Intermediate Casing 192 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>192</u>		
10 min	<u>0</u>		<u>190</u>		
15 min	<u>0</u>		<u>191</u>		
20 min	<u>0</u>		<u>188</u>		
25 min	<u>0</u>		<u>188</u>		
30 min	<u>0</u>		<u>190</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>✓</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Nothing came out of Bradenhead but casing pressure fluctuated
alot.

By Chris Heclaust
Pumper
(Position)

Witness

E-mail address Cherbaug@bhep.com

