



NEW MEXICO DEPARTMENT OF REVENUE
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-19-07 Operator Black Hills API #30-0 39-26858

Property Name Tic 29-2-6 Well No. 3 Location: Unit Section 6 Township 29N Range 3W

Well Status (Shut-In or Producing) Initial PSI: Tubing 103 Intermediate Casing 103 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>103</u>		
10 min	<u>0</u>		<u>103</u>		
15 min	<u>0</u>		<u>102</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

Well has been temporarily abandoned, no separator or location
& no flow line to sales line

By Chris Hedberg
Pumpjack
(Position)

Witness

E-mail address Cherhauy@bhep.com

