



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX (505) 334-6170
<http://emnr.state.nm.us/ocd/DistrictIII/DistrictIII.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-6-07 Operator mm Production API #30-0 39-05432

Property Name Ticulla Apache Well No. 009 Location: Unit m Section 14 Township 34N Range 05W

Well Status (Shut-In or Producing) Tubing 70 Intermediate 0 Casing 72 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes	✓	✓	Down to Nothing	
20 minutes			Nothing	✓
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD NOV 6 '07
OIL CONS. DIV.
DIST. 3

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS

Well equalize casing & tubing
because Enterprise's line pressure
was going up.

By Billy Keetse
Pumper
(Position)

Witness Aurora McCann