Form 3160 DEPARTME	r reentry to a different reservoir Use "APPLICATION	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993  5. Lease Designation and Serial No. NMSF-078771  6 If Indian, Allottee or Tribe Name RCUD OCT 26 '07'
SUBMIT IN TRIPLICATE RECEIVED		7 If Unit or CA, Agreement Designation
Type of Well     Oıl Well X Gas Well Other	OCT 1 6 2007	8. Well Name and No. IST. 3  ROSA UNIT #14C
Name of Operator     WILLIAMS PRODUCTION COMPANY	Bureau of Land Management Farmington Field Office	9. API Well No 30-039-30132
3. Address and Telephone No. PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254		10. Field and Pool, or Exploratory Area BLANCO MV/BASIN DK
4. Location of Well (Footage, Sec., T, R, M., or Survey Description) 2505' FNL & 895' FEL SE/4 NE/4 SEC 23-T31N-R06W		11. County or Parish, State RIO ARRIBA, NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent  X Subsequent Report  Final Abandonment	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other <u>Set surface esg</u>	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*  10-07-2007 Drlg 14 ¾" hole section from 0' to 338' (TD surface hole). RU csg crew, RIH w/ 7 jts 10 ¾", 40.5#, K-55, ST&C csg, landed @ 328' on 10/06/07 @ 21:30 hrs. RU cementers, cmt 10 ¾" csg @ 328', shoe depth, sgl slurry cmt job, 20 bbls FW spacer, 280 sxs (395 cu.ft.) Type III cmt + 2% CaCl-2 + POL-E- Flake + 20 bbl water = 45 bbl, slurry @ 14.5 ppg. Displace w/ 28 bbl water, bump plug from 75 to 250 psi, PD @ 22:30 hrs, check float, good, 36 bbls cmt returns to surface, TOC on surface pipe @ surface_RD cementers, WOC, back out landing jt, NU BOP & related equip.  10-08-2007 BO landing jt, NU BOP & related equip. Cut drlg line, check drum brakes, ok. Test BOP & related equip, low test to 250 psi for 5 min, high test to 1500 psi for 10 min, test 10 ¾" csg to 2000 psi for 30 min, tested good. PU MM & 12 ¼" bit, re-drlg mouse hole, LD MM & 12 ¼" bit. PU 8" MM & 9 7/8" bit, TIH tag up @ 274', LD 3 X 6 ½" DC's. Rotary drlg cmt, insert float & shoe-jt-from-274' to 328', CO from 328' to 338'. Rotary drlg 9 7/8" hole section from 338' to 850'.  ACCEPTED FOR RECORD		
14. I hereby certify that the foregoing is true and of Signed Tracy Ross		Date October 14, 2007
(This space for Federal or State office use)  Approved by  Title  Date		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any: