



Deviation Report

Name of Company
D. J. Simmons, Inc.

Address
1009 Ridgeway Place, Suite 200
Farmington, New Mexico 87401

Lease Name and No.
Blanco Wash 27 #2

API Number
30-045-34107

Location (Ftg)
642'FNL, 1741'FWL

Sec, Twn-Rng
Sec. 27, T-24-N, R-8-W

Pool and Formation
Lybrook Gallup

County
San Juan

State
New Mexico

Survey Depth (ft)

Deviation (degrees)

401'	3.00
840'	2.50
930'	2.50
1021'	1.50
1116'	1.50
1209'	2.00
1302'	0.25
1395'	1.50
1459'	0.50
1900'	0.50
2026'	0.00
2116'	1.00
2206'	1.00
2329'	0.50
2458'	1.00
2590'	0.50
2841'	0.50
2900'	0.50
2987'	0.50
3092'	0.50
3260'	0.50
3466'	1.50
3580'	0.50
3676'	0.50
3800'	1.00
3930'	1.00
4220'	1.00
4487'	1.00
4673'	1.00
4872'	1.00
5216'	1.00
5371'	0.50
5579'	0.50

RCVD DEC 20 '07

OIL CONS. DIV.

DIST. 3

Air Hammer Used? Yes

No

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for D. J. Simmons, Inc., am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and the facts stated herein are true and to the best of my knowledge and belief.

Rodney Z. Seale 12-19-07
Project Engineer

Subscribed and sworn to before me on December 19, 2007

Nancy Oltmann
Notary Public in and for San Juan County, New Mexico
My Commission expires on September 22, 2008

8