



## Deviation Report

**Name of Company**

D. J. Simmons, Inc.

**Address**1009 Ridgeway Place, Suite 200  
Farmington, New Mexico 87401**Lease Name and No.**

Blanco Wash 26 #1

**API Number**

30-045-34119

**Location (Ftg)**

1773'FSL, 1593'FWL

**Sec, Twn-Rng**

Section 26, T-24-N, R-8-W

**Pool and Formation**

Lybrook Gallup

**County**

San Juan

**State**

New Mexico

**Survey Depth (ft)****Deviation (degrees)**

161'	1.00
420'	1.50
640'	1.00
927'	1.00
1240'	1.50
1398'	1.00
1521'	0.50
1835'	1.00
2145'	1.00
2424'	1.00
2801'	1.00
3110'	1.00
3424'	1.00
3765'	1.00
4170'	0.50
4480'	1.00
4767'	0.50
5080'	0.50
5363'	0.50

RCVD DEC 20 '07

OIL CONS. DIV.

DIST. 3


Air Hammer Used? Yes

☒ No

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for D. J. Simmons, Inc., am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and the facts stated herein are true and to the best of my knowledge and belief.

  
Project Engineer

Subscribed and sworn to before me on December 19, 2007

  
Notary Public in and for San Juan County, New Mexico  
My Commission expires on September 22, 2008

88