



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1/22/08 Operator DJ Simmons API #30-0 39-27262
Property Name Burnet 24 Well No. 1 Location: Unit 24 Section 24 Township 25 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 10 Intermediate NA Casing 15 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min						
10 min						
15 min						
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing		
Nothing	✓	
Gas		
Gas & Water		
Water		

RCVD JAN 22 '08
OIL CONS. DIV.
DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

Nothing when opened. - producing through
Casing not tubing - what I thought was an intermediate
p.l. was just another valve to casing

By [Signature]
Field Tech
(Position)

Witness [Signature]

E-mail address _____