



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD,
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1/22/08 Operator DJ Simmons API #30-0 37-27556
Property Name Burnet 34 Well No. 1R Location: Unit E Section 24 Township 25 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 65 Intermediate 63 Casing 63 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min					<u>63</u>
10 min					<u>52</u>
15 min					<u>50</u>
20 min					<u>49</u>
25 min					<u>45</u>
30 min					<u>44</u>

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	☒
Surges	
Down to Nothing	☒
Nothing	
Gas	☒
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 48

REMARKS:

BH blew down in 6 seconds (Whispered down)
(1/4" nipple on intermediate - did not blow down)

By [Signature]
Field Tech
(Position)

Witness [Signature]

E-mail address _____