

ORL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC MM 87410
(505) 334-8178 FAX: (506) 334-8170
http://emmrd.state.nm.us/ocd/District BU3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test	1-28-08	Operator	ENERDYNE LLC	API #30-0	31-05395
Property Name_RE	ED MOUNTAIN I	Well No. 028	Location: Unit OS	ection 20 Tox	vnship 20N Range 9W
Well Status(Shut-	In or Producing	g) Tubing 5/8" In	ntermediate NA Casi	ng 4.5" Branc	denhead NA
OPEN BRADEN	IHEAD AND IN	TERMEDIATE TO	ATMOSPHERE INDIV	/IDUALLY FOR	15 MINUTES EACH
PRESSURES:				BRADENHEAD	
INTERMEDIATE TIME <u>IN</u>	TERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing	g	
20 minutes			Nothing	,, <u>,</u>	
25 minutes			Gas		FCVD JAN 30'08
30 minutes			Gas & Water	···	on cons. Dill
			Water	· · · · · · · · · · · · · · · · · · ·	
If bradenhead flowed water, check all of the descriptions that apply below:					DIST. 3
CLEAR	FRESH	SALTY	SULFUR BLAC	rk.	
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE					
REMARKS: SHAL	LOW MENEFE	WELL THAT PRO	DUCES FRESH WATER	R WITH OIL- PRO	DDUCTION CASING ONLY- N
SURFACE CASING OR BRADENHEAD.				4/2 7	To 453'
By DON L. HANOSH		Witness_			
MANAGING M (Position)	EMBER				