

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(506) 334-8178 FAX: (506) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test_	1-28-08	Operator_	ENERDYNE LLC	API #30-0	31-20623
			Location: Unit B Se		
Well Status(S	hut-In or Producin	g) Tubing <u>5/8"</u> I	ntermediate NA Casin	g 4.5" Branden	head NA
OPEN BRA	DENHEAD AND I	NTERMEDIATE TO	ATMOSPHERE INDIVI	DUALLY FOR 15	MINUTES EACH
PRESSURES:			BRADENHEAD		
INTERMEDIAT TIME	E INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing	RC	80'08 NAL DV
			Nothing	0	L CONS. DIV.
25 minutes			Gas		'
			Gas & Water		DIST. 3
			Water		
<u>If bradenhead f</u>	lowed water, check a	ll of the descriptions t	hat apply below:		
CLEAR	FRESH	SALTY	SULFUR BLACK	(
e miniite chi	UT IN DD AISENIU	EAD	INTERMEDIATE		
	UI-IN BRADENH	EAD	INTERMEDIATE	unia.	
REMARKS: S	SHALLOW MENEFE	E WELL THAT PRO	DUCES FRESH WATER	WITH OIL- PRODI	UCTION CASING ONLY- N
SURFACE CASING OR BRADENHEAD.				2.375 7	0 299'
 					
By DON L. H	IANOSH	Witness			
	IG MEMBER	-			
(Positio	on)				