

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1900 RIO BRAZOS ROAD
AZTEC NM 87410
(506) 334-6178 FAX: (506) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 1-28-08	Operator	ENERDYNE LLC	API #30-0 31	-20646
Property Name CHACO WASH M				
Well Status(Shut-In or Producing)	Tubing 5/8" In	termediate NA Casin	g 4.5" Branden	head_NA
OPEN BRADENHEAD AND IN	TERMEDIATE TO	ATMOSPHERE INDIV	IDUALLY FOR 15	MINUTES EACH
PRESSURES: INTERMEDIATE			BRADENHEAD	
TIME INTERMEDIATE	CASING	<u>-</u>	FLOWED	FLOWED
5 minutes_		Steady Flow		
10 minutes		Surges		
15 minutes		Down to Nothing		<u>80'08 // U</u>
20 minutes				L CONS. DIV.
25 minutes	مشوف برجون يورد سيخطعه	Gas		DIST, 2
30 minutes			1	
		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEARFRESH	SALTY	SULFUR BLACE	ζ.	
5 MINUTE SHUT-IN BRADENHE.	AD	INTERMEDIATE		
REMARKS: SHALLOW MENEFEE	WELL THAT PROD	DUCES FRESH WATER	WITH OIL- PROD	JCTION CASING ONLY- N
SURFACE CASING OR BRADENHEAD.			1 0	
		<u> </u>		
By DON L. HANOSH	Witness_			
MANAGING MEMBER (Position)				