

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 67410 (505) 334-5178 FAX; (506) 334-6170

www.emrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2/7/0 2	9 Operator	BMG	_API #30-0 <u>39</u> -	82274
Property Name <u>EPCMU</u> Well No. <u>18</u> Location: Unit <u>P</u> Section <u>13</u> Township <u>27/18</u> Range <u>1</u> Location				
Well Status (Shut-In or Pro	ducing) Tubing O	Intermediate // Cas	ing 15 Bradenho	ead 0
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRE TIME <u>BRADENHEAD IN</u>	ESSURES: NTERMEDIATE CASING	_	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes O		Steady Flow		
10 minutes O		Surges		
15 minutes O		Down to Nothin	g	
20 minutes		Nothing	K	
25 minutes				
30 minutes		Gas & Water		
		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
S MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE				
REMARKS:				
			F	CVD FEB 11'08
				DIL CONS. DIV.
_	A A =	_		DIST. 3
By Ban Longo	les	Witness		
The state of the s				
(Position)				
E-mail address				