



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrur.state.nm.us/ocd/District 03/district.htm](http://emrur.state.nm.us/ocd/District%203/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 12/31/08 Operator CHEVRON MID CONT API #30-0 3907007
Property Name RINCON Well No. 116 Location: Unit D Section 21 Township 27 Range 6W
Well Status(Shut-In or Producing) Tubing 90 Intermediate 107 Casing 107 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>107</u>	Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE

REMARKS:



By U. Over
MAINT PLANNER
(Position)

Witness