



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2/7/08 Operator: Elm Ridge Exploration CO LLC API #30-039- 23440
Property Name Martin Whitaker Well No. 34 Location: Unit 0 Section 16 Township 23 Range 4
Well Status (Shut-In or Producing) Tubing 95 Intermediate 0 Casing 201 Bradenhead 16

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>NA</u>	<u>202</u>	Steady Flow	
10 minutes	<u>0</u>	<u>NA</u>	<u>205</u>	Surges	
15 minutes	<u>0</u>	<u>NA</u>	<u>206</u>	Down to Nothing <u>X</u>	
20 minutes	<u>0</u>	<u>NA</u>	<u>207</u>	Nothing	
25 minutes	<u>0</u>	<u>NA</u>	<u>208</u>	Gas	
30 minutes	<u>0</u>	<u>NA</u>	<u>210</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Bradenhead took 3 min to Blow Down!



By R. J.

Witness _____

Pumper
(Position)

E-mail address _____