

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test <u>2/7/08</u>	_ Operator: Elm F	Ridge Expl	loration CO LLC A	PI #30-043-	20	169
Property Name Motion	Wh; Hakerwell	No. 76	Location: Uni 6	Section 20	Γownship	2Range
Well Status Shut-In or 1	Producing) Tub	ing_ () I	ntermediate MA Cas	ing () B	radenhea	d_ O
OPEN BRADENHEAD	AND INTERME	DIATE TO	ATMOSPHERE INDIV	VIDUALLY I	FOR 15 M	INUTES EACH
	PRESSURES: INTERMEDIATE	CASING		BRADENHI FLOWED	EAD	INTERMEDIATE FLOWED
5 minutes			Steady Flow			
10 minutes			Surges			
15 minutes		ĺ	_ Down to Nothin	g		
20 minutes			Nothing	X		
_25 minutes			Gas	· <u>··········</u>		***************************************
30 minutes			Gas & Water			
			Water			
If bradenhead flowed water	; check all of the de	escriptions t	hat apply below:		227	324 2526272
CLEAR FF	RESH SAL	TY	SULFUR BLACE	Κ	S P	ECEIVED
Water						
Well NOT Prod! Down Hole Problem!						
ву Д			Witness			
Pumper						
(Position)						
E-mail address						