



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178

FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2-26-08 Operator CO LLC API #30-0 39-24754
Property Name Lybrook South Well No. 9 Location: Unit K Section 18 Township 23^N Range 6^W
Well Status (Shut-In or Producing) Tubing NA Intermediate NA Casing 110 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	0		110	Steady Flow	
10 minutes	0		110	Surges	
15 minutes	0		110	Down to Nothing	✓
20 minutes	0		110	Nothing	
25 minutes	0		110	Gas	✓
30 minutes	0		110	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Bradenhead pressure NOT enough to register on gauge - opened
valve - puff of gas down to nothing.

By Jac J. Louato, Jr.

Witness _____

(Position)

E-mail address _____

