



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2-6-08 Operator: Elm Ridge Exploration CO LLC API #30-039- 24908

Property Name Blanco Gb 6 Well No. 5 Location: Unit G Section 6 Township 23<sup>N</sup> Range 7<sup>W</sup>

Well Status (Shut-In or Producing) Tubing na Intermediate na Casing 70 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes				Steady Flow	
10 minutes				Surges	
15 minutes				Down to Nothing	
20 minutes				Nothing <u>Braden head Flowed</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

NO TUBBING IN WELL

By [Signature]

Witness \_\_\_\_\_

Pumper  
(Position)

E-mail address \_\_\_\_\_

