



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2-26-08 Operator Elm Ridge Exploration CO LLC API #30-039-24938  
Property Name Lybrook South Well No. 5 Location: Unit M Section 13 Township 23<sup>N</sup> Range 7W  
Well Status (Shut-In or Producing) Tubing NA Intermediate NA Casing 70 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>70</u>	Steady Flow	
10 minutes	<u>0</u>		<u>70</u>	Surges	
15 minutes	<u>0</u>		<u>70</u>	Down to Nothing	
20 minutes	<u>0</u>		<u>70</u>	Nothing <u>✓</u>	
25 minutes	<u>0</u>		<u>70</u>	Gas	
30 minutes	<u>0</u>		<u>70</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

By Joe J. Rouds

Witness \_\_\_\_\_

Pumper  
(Position)

E-mail address \_\_\_\_\_

