



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

*Elm Ridge Exploration*

Date of Test 2-22-08 Operator CO LLC API #30-039-24557

Property Name M<sup>z</sup> Bee 7 Well No. 54 Location: Unit E Section 7 Township 23<sup>N</sup> Range 6<sup>W</sup>

Well Status (Shut-In or Producing) Tubing 75 Intermediate NA Casing 130 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>130</u>	Steady Flow	
10 minutes	<u>0</u>		<u>130</u>	Surges	
15 minutes	<u>0</u>		<u>130</u>	Down to Nothing <input checked="" type="checkbox"/>	
20 minutes	<u>0</u>		<u>130</u>	Nothing	
25 minutes	<u>0</u>		<u>130</u>	Gas <input checked="" type="checkbox"/>	
30 minutes	<u>0</u>		<u>130</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE     

REMARKS:

Bradenhead pressure not enough to register on gauge - opened  
valve - puff of Gas - down to nothing.

By Joe J. Louato, Jr.

Witness     

Pumper  
(Position)

E-mail address     

