

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 2/22/08	Coperator: Elm I	Ridge Exp	loration CO LLC A	PI #30-0 <u>3</u>	9-23804
Property Name Sicaril	19 491 Well	1 No. 1	Location: Unit S	ection <u>3</u> To	wnship Range
Well Status (Shut-In or	Producing) Tub	oing <u>9</u> 7	Intermediate Casi	ing // 3 Brac	denhead
OPEN BRADENHEA	D AND INTERME	DIATE TO	ATMOSPHERE INDIV	'IDUALLY FOI	R 15 MINUTES EACH
TIME <u>BRADENHEAD</u>	PRESSURES: INTERMEDIATE	CASING		BRADENHEA FLOWED	D INTERMEDIATE FLOWED
5 minutes <i>D</i>		113	Steady Flow		
10 minutes <i>O</i>		113	Surges		
15 minutes <u>O</u>		113	_ Down to Nothing	) 	
20 minutes			Nothing <b>Y</b>		
25 minutes	<u> </u>				
30 minutes	<u></u>		Gas & Water		
			Water		
If bradenhead flowed water	r, check all of the de	escriptions (	that apply below:	_	
CLEARF	RESHSAL	TY	SULFUR BLACK		8293037
5 MINUTE SHUT-IN BRADENHEAD REMARKS:			SULFUR BLACK		
				6181	(1910 the Sty
		··			
		·			
Ву			Witness		
Pumper Like (Position)	Dur				
E-mail address				,	