

E-mail address: brads@titusconsulting.net

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

| (| |
|---|---|
| Date of Test 9-19-07 Operator BLUE DOLPHIN | N PRODUCTION LLC. API #30-039-29587 |
| Property Name EL POSO Well No 7 Location: | Unit E Section 26 Township 28N Range 1E |
| Well Status (Producing) Tubing P-4 Intermed | diate NA Casing SI-11 Bradenhead SI-0 |
| OPEN BRADENHEAD AND INTERMEDIATE TO | O ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH |
| PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING | BRADENHEAD INTERMEDIATE FLOWED FLOWED |
| 5 minutes 0_psi | Steady Flow |
| 10 minutes | Surges |
| 15 minutes | Down to Nothing |
| 20 minutes | Nothing |
| 25 minutes | Gas |
| 30 minutes | Gas & Water |
| | Water |
| If bradenhead flowed water, check all of the descriptions t | that apply below: |
| CLEAR FRESH SALTY | SULFUR BLACK |
| 5 MINUTE SHUT-IN BRADENHEAD_0 psi | INTERMEDIATE |
| REMARKS: Open bradenhead. No Pressure. | |
| • | |
| | RCVD MAR 3 '08 |
| | OIL CONS. DIV. |
| By B.W. Salzman | nist. a |
| By_B.W. Salzman Consultant (Position) | Witness |